# Exhibit 48

ADVANCED CARDIOVASCULAR SYSTEMS

START TIME: FINISH TIME:

30 2 G

EXTRUSION #: 10-605-1 AMOUNT (FEET): 7000DATE: 6-20-94 SIGNATURE/DATE AM 6-20-94

MATERIALS:

MATERIAL DESC. \_\_\_\_\_\_ LOT# :

RM#

\_\_\_\_\_ PEEK VICTREX

REQUESTOR S SCHAIBLE (Evic helped)

PRODUCT SHAFT (1211) SA#

SET-UP PARAMETERS: \_\_\_\_\_\_

MANDREL LGTH (EXT ONLY) FLUSH

EXPERIMENTAL Y

DIE I.D. .199

OVAL N ROUND Y

PRODUCTION N

MANDREL O.D. .166 XHEAD Y

PE 4770-3

STRAIGHT N

SCREW TYPE

SCREEN TYPE 20 80 20

START ID/OD .028/.034

FINISH ID/OD .028/.034

## PROCESS PARAMETERS

TEMPERATURE SETPOINTS	SPEEDS &	SETPOINTS	PSI & AIR
ZONE 1 566.0 MELT 77	79 <del>0.0</del> SCREW RPM 32.0 PSI SET	2.0	HEAD PSI 18.0
ZONE 2 650.0 DIE 1	32.0 PSI SET	770.0	DIE PSI -500.0
ZONE 3 715.0 DIE 2	0.0 EXTR. AMP		AIR PSI 1 0.2
CLAMP 715.0 DIE 3	715.0 PUL SPEED	<del>-53</del> -45-0	2  (0.4)
INLET 715.0 W/B TEMP	OTO W/B DIST.	O WATER	3  0.3
G/PUMP 0.0			4 0.4

PMP-OUT-342.0

XHEAD 0.0

MATERIAL DRYING TMP. 320 DEWPOINT - 67 # OF HRS DRYING 72 has

### ACTUAL PARAMETER COLLECTED EVERY 10 MINUTES

SETPOINT	ACTUAL 6	ACTUAL 7	ACTUAL 8	ACTUAL 9	ACTUAL10
G/PUMP PSI	787	1084	273	175	0
PUMP AMP	0	0	O	0	0
SCREW RPM	2	8	24	24	0
EXTRUDER AMP	13	8	7	7	0
PULLER SPEED					
BARREL 1	799	1046	173	56	19
BARREL 2	0	0	0	0	O
BARREL 3	0	0	0	0	0
HEAD PSI	787	1084	273	175	O
TUBING O.D.	0.0000	0.0000	0.0000	0.0000	0.0000
AVG.DIA.	0.0000	0.0000	0.0000	0.0000	0.0000
AVG.STD.DEV.	0.0000	0.0000	0.0000	0.0000	0.0000

# ADVANCED CARDIOVASCULAR SYSTEMS

EXTRUSION DATA SHEET START TIME:

EXTRUSION #: 10-604-1 AMOUNT (FEET): 1,000
DATE: 6-20-24 SIGNATURE/DATE

FINISH TIME:

LOT# : MATERIALS : MATERIAL DESC. RM# \_\_\_\_\_

PEEK VICTREX

EXTRUDER 10 PROCESS PERSON T. TOMAS

REQUESTOR S SCHAIBLE

PRODUCT SHAFT SA#

SET-UP PARAMETERS:

, Programa

MANDREL LGTH (EXT ONLY) FLUSH EXPERIMENTAL Y OVAL N DIE I.D. .199 ROUND Y PRODUCTION N

MANDREL O.D. .166 XHEAD Y STRAIGHT N

SCREW TYPE PE 4770-3 SCREEN TYPE 20 80 20 START ID/OD .032/.038 FINISH ID/OD .032/.038

#### PROCESS PARAMETERS

TEMPERATURE SETPOINTS		SPEEDS & SETPOINTS	PSI & AIR
ZONE 1 5655.0 MELT 779	0.0	SCREW RPM 2.2	HEAD PSI 774.0
ZONE 2 650.0 DIE 1		PSI SET 777.0	DIE PSI 773.0
ZONE 3 715.0 DIE 2	0.0	EXTR. AMP 12.2	AIR PSI 1 0.2
CLAMP 715.0 DIE 3	715.0	PUL SPEED 53	2 0.3
INLET 715.0 W/B TEMP	0.0	W/B DIST. O WATER	3 0.3
G/PUMP 0.0			4 0.4
DMD OUT EEE O			

PMP OUT 555.0 0.0

MATERIAL DRYING TMP. 300 DEWPOINT -67 # OF HRS DRYING 72 hrs

## ACTUAL PARAMETER COLLECTED EVERY 10 MINUTES

SETPOINT	ACTUAL 1	ACTUAL 2	ACTUAL 3	ACTUAL 4	ACTUAL 5
G/PUMP PSI	856	814	839	776	773
PUMP AMP	0	0	0	0	0
SCREW RPM	2	2	2	2	2
EXTRUDER AMP	12	12	11	12	11
PULLER SPEED					
BARREL 1	883	890	853	785	799
BARREL 2	0	0	0	0	0
BARREL 3	0	0	0	0	0
HEAD PSI	856	814	839	776	773
TUBING O.D.	0.0000	0.0000	0.0000	0.0000	0.0000
AVG.DIA.	0.0000	0.0000	0.0000	0.0000	0.0000
AVG.STD.DEV.	0.0000	0.0000	0.000	0.0000	0.0000